

Error Code Buffer (Continued)

Should an error occur, the information contained within the Error Buffer will help the Service Personnel remedy the current problem and prevent any similar problems arising in the future.

The Error codes are as follows

| Error Code | Description |
|------------|--|
| 0(n) | Etote error on module (n) |
| 07 | Etote assembly communication error |
| 1(n) | Pulser count error on module (n) |
| 2(n) | Reverse flow on hydraulics module (n) |
| 3(n) | Pulser power supply circuit on hydraulics module (n) |
| 40 | Transaction display error |
| 41 | Incomplete main display update or GMI pulses not all output on power fail |
| 45 | GMI board has reported an error – either fuelling point |
| 46 | GMI Volume pulse accumulation on either fuelling point has exceeded 5 litres |
| 47 | GMI Cash pulse accumulation on either fuelling point has exceeded 500 cash units |
| 50 | Database value out of range – corrected |
| 51 | Restore data checksum failed |
| 52 | EEPROM device check reports failure |
| 53 | Too many writes to EEPROM |
| 54 | Software variable set to default value after memory corruption |
| 55 | Invalid parameter passed to database in a call from software task |
| 56 | The claim and release database functions incorrectly used by software |
| 57 | Volume total or pulse count for a delivery has been corrupted |
| 60 | Incorrect gas detector valve configuration setting or faulty wiring |
| 6(n) | Gas detected during delivery on hydraulics module (n) |
| 7(n) | Blend error |
| 71 | Oil Level error or oil pulse error |
| 8(n) | Vapour recovery hose leak on module (n) |
| 90 | Communications error (Device Busy ie. More than 10 buffers in use) |
| 95 | Background EPROM check reports failure |
| 96 | Multitasking executive error |
| 97 | Software stack overflow |
| 98 | Software execution boundary violation |
| 99 | Watchdog timeout (failure) |
| 101-125 | Stack overflow for task nnn (normally error 97 for undefined task) |
| 140 | EPSIF Task watchdog timeout |
| 141 | Buffer overrun (more than 384 bytes in one message) |
| 150 | Neuron active sensing timeout |
| 160 | Two-wire communications protocol error |

Note: Error codes apply to a range of HARDWARE configurations.
NOT ALL CODES APPLICABLE TO ONE SYSTEM.