

## Error Codes

### Pacesetter and Retro 700's

Error 1	Pulsar Error	If fault occurs 2 or 3 times in a row serviceman required.
Error 2	Calculation Error	Turn Power off and on
Error 3	Price Change	Clears after one Min

### Multi Product Pumps

#### *Processor Errors*

Error 8	CPU Error	CPU Board Faulty
Error 9	CTC Timer Error	CPU Board Faulty

#### *Pulsar Errors*

Error 11	Cross Check Error
Error 12	Excess Reverse Counts
Error 13	Excess Pulse Rate
Error 14	Fuel Flow on now selected Hose

#### *Range Errors*

Error 37	Ram Error	CPU Board
Error 38	Eprom Error	CPU - Tote Board
Error 39	Eprom A Error	Tote Board
Error 40	Eprom B Error	Tote Board
Error 41	Illegal Unit Price Value (> 499.9 cents / Litre )	CPU - Tote Board
Error 42	Illegal 'K' Factor (> 200,000 ml's s/pulse )	CPU - Tote Board
Error 43	Bounds Error	CPU - Tote Board
Error 44	Pump Number Switch set to 0	CPU Board

#### *Over Run Errors*

Error 50	Major Cycle Task Over run	CPU Board
Error 51	Test Task Over run	CPU Board

#### *Restart Errors*

Error 60 to Error 67	Power related Faults and can also be caused by faulty connections on internal wiring or cable.
----------------------	------------------------------------------------------------------------------------------------

ERROR 23 - LPG ERROR WHEN TEMP PROBE ISN'T DISSABLED